

Zone d'entretien du TUF

A photograph of a stream flowing through a natural, somewhat overgrown area. The water is clear and flows over a bed of rocks and sand. The banks are lined with various plants, including tall grasses on the right and dense, white-flowered shrubs on the left. A red arrow points from the text '1,5m de large' to a specific section of the stream. Another red arrow points from the text 'Aval de la zone d'entretien du TUF' to the same section of the stream.


Aval de la zone d'entretien du TUF

1,5m de large

Lit avant travaux 4 m de large plein bord



Lit emboité après travaux 1 m de large, connexion amont aval



Lit avant travaux 4 m de large plein bord

Lit emboité après travaux 1 m de large, connexion amont aval